

## Industrial, High-Speed and Specialty Doors

### New Sliders Update Original Doors

A local farmer had an old, well-constructed building on his property. However, his original wood sliding doors were starting to rot.

Before



After



#### PROBLEM

For the most part, the doors of the existing building were fine. The only issue was they had begun to rot on the bottom.

The farmer wanted to keep the original doors, but needed a good solution to help him deal with the rotten wood.

#### SOLUTION

DH Pace cut off the rotten wood, replaced it with new wood and then wrapped it with aluminum brake metal. Then the team installed a new leading edge and replaced the old weather seals with new brush seals on all sides to keep the elements out.

#### CONCLUSION

DH Pace can offer simple solutions to ensure original structures continue to keep their original look, design and functionality.